

Technician:

International Road Dynamics Inc.

Site Service Sheet

Raymond Pollon

Clear

	Bending Plate				System Type: iSINC			
Date: <u>Sep/05/201</u> Job #: <u>11378</u>		AR	· · · · · · · · · · · · · · · · · · ·					
	Lane - 1		Lane -		Lane -		Lane -	
Loops	Lead	Trail	Lead	Trail	Lead	Trail	Lead	Trail
Resistance	1.60Ω	1.70Ω						
Leakage	∞	∞						
Inductance								
Frequency	75.0KHz	77.5KHz						
	Lane - 1		Lane -		Lane -		Lane -	
Weighpads	Lead	Trail	Lead	Trail	Lead	Trail	Lead	Trail
Supply	996Ω	997Ω						
Signal	850Ω	851Ω						
Shield	∞	8						
Zero Pt	0.15 mV	0.17mV						
Serial #								
Piezos	Long		Lane -		Lane -		Lane -	
Amplitude	Lane -		Laile -		Lane -		Laile -	
Capacitance							1	
Resistance								
. 100.01000				ı				
System Temp Sensor								
A/C Service	121 VAC		Red	to Blk	n/a			
Power Supply	13.5	Red	Red to Wht					
Solar Panel	N/A		Wh	t to Blk				
Back-Up	13.5 VDC							
System Input	N/A							
Modem Power	13.5 VDC							
Phone off hook								
Phone on hook								

SEPT-06-2011

Date: